Easy Steps To Great Sno-Kones



- 1. Load the gooseneck with ice cubes. Fill to about an inch or so from the top.
- 2. Push the motor button in to start.
- 3. Push down on the handle to press the ice against the cutter head. A firm even pressure is best. Never force. More pressure on the handle gives coarser ice. Lighter pressure on the handle gives finer ice.
- 4. Relieve the pressure two or three times on the way down. This lets the ice rearrange itself and you will get a better bite.
- 5. **Be cautious** not to put fingers in the gooseneck tube or get jewelry in the way of the cutter. Injury can occur.
- 6. Fill cones to about half way with ice. Then with scoop fill the rest of the way to make the top rounded. Pour syrup in circular motion over the top until the ice is covered with the colored fluid.
- 7. The machine and supplies need to be clean before returning. Unplug the machine from electricity and wipe down.

Supplies Needed

50 lbs. of ice + 1 gallon of syrup =

100 sno-kones

Children
should not be
permitted to operate
machine without
adult supervision

